

ATC Software Release Version 8.7.0.x

Notes are changes from version 8.6.0.4

Release Date: September 24, 2018

New Features

1. Added support for face verification during device access
2. Automatic internal network configuration during startup can be disabled by a device's configuration file

Bug Fixes

1. #762 - Pressing Max window button on calibration data screen locks up system
2. #763 - Calibration data screen can have both rgb gain sub menu and target intensity sub menu active simultaneously
3. #766 - Admin main window title is "ATC Administration Application" [sic]
4. #767 - New calibration dot strips caused the contrast to be too low for reliable exposure control during calibration.
5. #768 - If the Disk Write Cache is enabled data could be lost and the system (OS, database, etc.) corrupted if the OS is improperly shutdown.
6. #769 - A SQL deadlock occurred while trying to upload new tools after a drawer training. The service swallows the error so the transfer is never re-attempted. Every log action that references any of the tools from that drawer will fail and cause the device to disconnect